



Firmware Release Notes: EXCERIA PLUS SSD

Version ECFA10.8 (10.3, 10.4, 10.5, 10.7 --> 10.8) June 13, 2024

Important: For EXCERIA PLUS SSD with ECFA10.3, 10.4, 10.5 and 10.7 firmware update aims to address critical bugs and/or improve the reliability and performance of your SSD. It is strongly recommended that you update your SSD.

Improvements

- Fixes bug.
- Changed the setting value of WCTEMP (Warning Composite Temperature Threshold) defined in Identify Controller Data Structure.

How to update SSD firmware

To update your SSD firmware, install/update the appropriate and latest SSD Utility Management Software for your SSD. Follow available user guide instructions and make sure to read all warnings and backup all your data before updating the firmware.